Service/Maintenance Check List

This form must not be used as a landlord gas safety record



Registered business		Job address		Landlord/age	ent
Gas safe id: 559616 ECS Plumbing and Heating Ltd Unit 9, The Stoneyard The Stoneyard Alton Lane Four Marks Hampshire GU34 5AJ +44 1420 571 000		The Village Hall Church Lane Holybourne Alton Hampshire GU34 4HD		Holybourne Village Hall The Village Hall Church Lane Holybourne Alton Hampshire GU34 4HD +44 7510 982 156	
Appliance					
Type of work	Service		Location		Boiler Room
Туре	Condensing Boilers		Make		Vaillant
Model	Ecotec plus 438		Serial number		21143300100061565n3
Gas tightness test	Ecolec plus 436		Schai humber		21143500100001303113
Type of gas tightness test?	Gac inc	tallation			
Preliminary gas tightness test	Gas installation Passed		Post and tightness tost		Passed
	Passeu		Post gas tightness test		Passeu
Analyser readings (Low)					
Low fire readings performed?					
CO ppm			CO2 %		
02 %			CO/CO2 ratio		
Flue gas temperature °C			% exAir %		
Analyser readings (High)			•		
High fire readings performed?	Yes				
Working pressure at meter mbar	19.00 Mbar		Appliance burner pressure mbar		N/A Mbar
Appliance inlet pressure mbar	13.70 Mbar		Gas rate m³/h or KW		m³/h
CO ppm	85 Ppm		CO2 %		8.9 %
O2 %	5.3 %		CO/CO2 ratio		0.0010
Flue gas temperature °C	35 °C		% exAir %		33.8 %
Appliance checks	Checke	d	Comments		
Location	Yes				
Burner/injectors	Yes				
Heat exchanger	Yes				
Ignition	Yes				
Electrics	Yes				
Controls	Yes				
Gas/water leaks	Yes				
Gas connections	Yes				
Seals (appliance case etc)	Yes				
Gas pipework	Yes				
Fan(s)	Yes				
Flue integrity test	Yes				
Fireplace opening/void					
Closure plate					
Flame picture					
Stability	Yes				
Expansion vessel	Yes				
EXPANSION VCSSCI	103		<u> </u>		

Safety checks	Checked		Comments			
Ventilation	Yes					
Flue termination	Yes					
Flue flow test						
Spillage test						
Operating pressure or heat input	Yes					
Safety device(s)	Yes					
Condensate	Yes					
Clearances	Yes					
Return air	Yes					
Findings		Outcome	Comments			
Is the appliance/installation safe t	Yes					
Gas supply been isolated/disconnected?						
Has a warning label been attached?						
Has a warning notice (CP14) been issued?						
The following remedial work is rec	quired					
Additional comment						
Engineer information	Received by information		on	Certificate information	Certificate information	
Engineer name Thomas Liddon	Name			Number	1320	
Gas safe card id	Receiv	,	stomer	Next service date		
Signature	Signat	ure		Report date	Fri 29 Aug 2025	
/ /						
1 /						